

Baird Park

Parking

There is no designated accessible parking at the Babe Ruth Field or around the Dixie Youth and two adjacent girl's softball fields. There is no van accessible parking at the Kiwanis Fields or the closest lots to Veteran's Field and the LGSA Fields. There are two van accessible spaces in the lot between Veteran's and the LGSA Fields, but they are not identified as van accessible. The ramp from these spaces to Veteran's Field has about a 1:24 cross slope. Three of the five designated spaces at the LGSA Fields have cross slopes between 1:18 and 1:24.

ADAAG: Where parking spaces are provided, accessible parking spaces shall be provided in accordance with 208 (208.1). For every six or fraction of six accessible parking spaces required, at least one shall be a van parking space complying with 502 (208.2.4). Cross slope of ramp runs shall not be steeper than 1:48 (405.3). Vehicle spaces and access aisles serving them shall have slopes not steeper than 1:48 (503.4).

Bleachers

The bleachers at Veteran's Field have cutouts providing wheelchair-seating locations. None of the other bleachers have cutouts but they are all on asphalt. The third base line bleachers at the Dixie Youth Field and one of the two adjacent girl's softball fields have a 1:18 slope about a foot back from the front of the bleachers. All of the other bleachers have a level paved area around them.

ADAAG: Wheelchair spaces complying with 802.1 and 221.2 shall be provided in assembly areas with fixed seating (221.2). The floor or ground surface of wheelchair spaces shall have slopes not steeper than 1:48 (802.1.1).

Restrooms

None of the restrooms' signage includes Braille or raised characters. None of the lavatory pipes are insulated.

ADAAG: Interior and exterior signs identifying permanent rooms and spaces shall include raised characters that comply with 703.1 that

are duplicated in Braille that complies with 703.2 (216.2). Water supply and drainpipes under lavatories shall be insulated or other wise configured to protect against contact (606.5).

Babe Ruth Field

The surface of the path to these restrooms is grass with a 1:9 to 1:10 slope right after the road. The doors have 29" openings and privacy walls, which create a 36" maneuvering space perpendicular to, and inside the doors. There is one larger stall in each room 56" and 57" deep with a back grab bar 20" long and a side bar 36" long. The men's room urinal is 29" high.

ADAAG: Floor and ground surfaces shall be stable, firm, and slip resistant (302.1). Ramp runs shall have a running slope not steeper than 1:12 (405.2). Door openings shall provide a clear width of 32" minimum (404.2.3). A latch, pull side approach requires a 48" maneuvering space perpendicular to the door (404.2.4.1). Wheelchair accessible compartments shall be 59" deep minimum for floor mounted water closets (604.8.1). The sidewall grab bar shall be 42" long minimum (604.5.1). The rear grab bar shall be 36" long minimum (604.5.2). Urinal rims shall be 17 inches maximum above the floor (605.2).

Dixie Youth and adjacent softball fields

The entrance to both of these restrooms is ramped and both have a 1:12 slope in the required maneuvering clearance on the latch side of the doors. At the bottom of the ramp to the men's room there is a 2" unbeveled change in the level where the concrete ramp meets the asphalt. There is one larger stall in each room that is 36 1/2" wide by 56" deep. These stalls have a grab bar behind the water closet that is 20" long and one alongside that is 36" long. There are six toilet stalls in the women's room.

ADAAG: Floor or ground surface within required maneuvering clearances shall have a slope of 1:48 maximum in any direction (402.2.4.4). Changes in level greater than 1/2" high shall be ramped and comply with 405 (303.4). Wheelchair accessible toilet compartments shall be 60" wide minimum and 59" deep minimum for floor mounted water closets (604.8.1). The sidewall grab bar shall be 42" long minimum (604.5.1). The rear grab bar shall be 36" long

minimum (604.5.2). Where six or more toilet compartments are provided, in addition to the wheelchair accessible compartment (604.8.1) at least one compartment shall be an ambulatory accessible compartment (604.8.2) 36" wide with parallel grab bars (213.3.1).

Kiwanis Fields

The entrances to both of these rooms are ramped but neither has a level landing in front of their door, instead there is a 1:12 slope. The ramps have more than a foot drop-off on both sides with no edge protection. The restrooms are not accessible. They are too small with stalls that are 32" wide by 40" deep with 28" door openings and no grab bars.

ADAAG: Edge protection complying with 405.9.1 or 405.9.2 shall be provided on each side of ramp runs and landings (405.9). Door openings shall provide a clear width of 32" minimum (404.2.3).

Veteran's Field

The restrooms in the Harold Greer building serve this field via their exterior entrances. The path from the bleachers to these rooms has a 1:9 slope in the vehicular way and then a 1:6 sloped ramp with no handrails. The exterior entrances have been ramped but their slopes go right to the door, no level landing.

ADAAG: Ramp runs shall have a running slope not steeper than 1:12 (405.2). Ramp runs with a rise greater than 6" shall have handrails complying with 505 (405.8). Floor or ground surface within required maneuvering clearances shall have a slope of 1:48 maximum in any direction (404.2.4.4).

LGSA Fields

There is a 2" doorstep at the entrance to the men's room. The doorstep has been beveled at the women's entrance.

ADAAG: Changes in level greater than ½" high shall be ramped to comply with 405 (303.4).

Concession Areas

The Dixie Field youth area is compliant with a 36" high counter. The two other adjacent softball fields have 38" and 39" high counters, and

the one in line with the Dixie Youth field has a 2" to 4" unbeveled change in level from the asphalt to the concrete pad at the counter. The Kiwanis fields' concession counters are 39 ½" high. The Babe Ruth concession counter is 42" high, and there is a 1" unbeveled change in level from the asphalt to the concrete pad. The concession counter at Veteran's field is 47" high. The LGSA fields' concession counter is 48" high.

ADAAG: At service counters, a portion of the counter surface which is 36" long minimum by 36" high maximum shall be provided (904.4.1).

Dugouts

The dugouts at LGSA fields are accessible. The Babe Ruth field dugouts can be accessed, but there is a 2" step to the bench in the dugouts. The Kiwanis fields, Dixie Youth field, and Blue Devilette's field have from 2" to 3" unbeveled changes in level to their dugouts' concrete pads. The Veterans field dugouts are inaccessible because of steps and steep slopes.

ADAAG: Changes in level greater than ½" high shall be ramped to comply with 405(303.4). Ramp runs shall have a running slope not steeper than 1:12 (405.2). Cross slope of ramp runs shall not be steeper than 1:48 (405.3).

Tennis Courts

There are less than 25 parking spaces provided. There are no designated accessible spaces.

ADAAG: Parking lots with 1 to 25 total spaces require a minimum of one van accessible space (208).

There is a 1:9 to 1:10 slope in front of the gate to the courts.

ADAAG: Floor or ground surface within required maneuvering clearances shall have a slope of 1:48 maximum in any direction (404.2.4.4).