

Elmer Elkins Park Hobbs Field

Parking

There is room for more than 100 parking spaces but there are no marked spaces and no designated accessible spaces.

ADAAG: Where parking spaces are provided, accessible parking spaces shall be provided in accordance with 208(208.1).

Path of Travel

The path to field two is dirt, gravel, and grass. There is a 4" step to field two's first base line bleachers.

ADAAG: Floor and ground surfaces shall be stable, firm, and slip resistant (302.1). Changes in level greater than 1/2" shall be ramped to comply with 405 or 406 (303.4).

Concession Counters

Field two's concession counter is 42" above the ground. Field one's counter is compliant at 30" high.

ADAAG: At service counters, a portion of the counter surface which is 36" long minimum by 36" high maximum shall be provided (904.4.1).

Restrooms

Field one restrooms have 27" wide door openings and field two restrooms have a 5" step up to them. None of the restrooms are designed, or equipped for accessibility.

ADAAG: Door openings shall provide a clear width of 32" minimum (404.2.3). Changes in level greater than 1/2" shall be ramped to comply with 405 or 406 (303.4).