

## Harold Greer Recreation Building

### Parking

There are 15 total spaces and two spaces are designated accessible. The spaces are not the closest to the entrance and there are no van accessible spaces.

**ADAAG:** Accessible parking spaces that serve a particular building shall be located on the shortest accessible route from parking to an accessible entrance (208.3.1). For every six or fraction of six accessible parking spaces required, at least one shall be a van space (208.2.4).

The parking spaces and access aisle have around a 1:30 slope and there is a built-up curb ramp in the access aisle.

**ADAAG:** Parking spaces and access aisles shall have slopes not steeper than 1:48 (502.3). Curb ramps and the flared sides of curb ramps shall be located so that they do not project into vehicular traffic lanes, parking spaces, or parking access aisles (406.5).

The built-up curb ramp is not flush with the sidewalk creating a ½ inch change in level.

**ADAAG:** Changes in level other than the running slope and cross slope are not permitted on ramp runs (405.4).

### Entry Foyer

The service counter is 51 inches above the floor.

**ADAAG:** At service counters, a portion of the counter, which is 36 inches long minimum by 36 inches high maximum, shall be provided (904.4.1).

### Interior Path of Travel

Door knobs for operating devices on office and meeting room doors. Some doors are hard to open.

**ADAAG:** Operable parts shall be operable with one hand and shall not require tight grasping, pinching, or twisting of the wrist (309.4).

The force required to push or pull open an interior hinged door shall be 5 lbf maximum (404.2.9).

### **Concession Counter**

The counter is 40 inches above the floor.

**ADAAG:** At service counters, a portion of the counter, which is 36 inches long minimum by 36 inches high maximum, shall be provided (904.4.1).

### **Restrooms**

Both rooms have 15 inches of maneuvering space on the latch, pull side of inward opening doors when exiting.

**ADAAG:** A front approach requires a minimum of 18 inches of maneuvering space to the latch, pull side of doors (404.2.4.1).

Both rooms have an accessible toilet stall with a back grab bar mounted 37 inches above the floor and extending to the corner. The stalls have toe clearance beneath their door but not their front partitions.

**ADAAG:** The top of grab bars shall be 33 inches minimum to 36 inches maximum above the floor (609.4). The front partition and at least one side partition shall provide a toe clearance 9 inches minimum above the floor, exclusive of partition support members (604.8.1.4).

The flush control on the water closet in the women's accessible stall is located on the wall side.

**ADAAG:** Flush controls shall be located on the open side of the water closet (604.6).

### **Drinking Fountains**

There is one drinking fountain with no knee space and a 40 inch high water spout.

**ADAAG:** No fewer than two drinking fountains, or a hi-lo fountain, shall be provided. Half of fountains shall be wheelchair accessible

(211.2). Accessible units shall have knee and toe space complying with 306 and water spouts 36 inches high maximum (602).