

Jimmy Floyd Family Life Center

Parking

The van accessible space is not designated van accessible.

ADAAG: Signs identifying van parking spaces shall contain the designation van accessible (502.6).

Exterior Path of Travel

There is an 8 foot long ramp with a 1:12 slope and no handrails between parking and the entrance.

ADAAG: Ramp runs with a rise greater than 6 inches shall have handrails complying with 505 (405.8).

Reception Counter

The counter is 42 inches above the floor.

ADAAG: At service counters, a portion of the counter, which is 36 inches long minimum by 36 inches high maximum, shall be provided (904.4.1).

Locker Rooms

Benches in the locker rooms, including the family locker rooms, are 9 inches wide with no back support.

ADAAG: A bench complying with 903 shall be provided within locker rooms (803.4). Benches shall have seats that are 20 inches minimum to 24 inches maximum in depth (903.3). The bench shall provide for back support or shall be affixed to a wall (903.4).

There is not a 60 inch by 60 inch turning space in the locker rooms or the changing rooms in the family locker rooms.

ADAAG: Wheelchair turning space complying with 304 shall be provided within dressing and locker rooms (803.2). Turning space shall be a space of 60 inches diameter minimum or a T-shaped space within a 60 inch minimum square (304.3).

Swimming Pool

There are indoor and outdoor pools and both have sloped entries, but no other accessible means of entry.

ADAAG: At least two accessible means of entry shall be provided for each public and common use swimming pool (15.8.1 proposed guidelines for Recreation facilities).

Snack Bar

The service counter and condiment counter are 39½ inches above the floor. Tables have 26 inch high knee space.

ADAAG: At service counters, a portion of the counter, which is 36 inches long minimum by 36 inch high maximum, shall be provided (904.4.1). Knee clearance shall be 27 inches high (306.3).

Restrooms

The centerline of the water closets in the nursery and family locker room toilet rooms are 23 to 24 inches from the side wall. The side grab bars are 36 inches long at accessible water closets.

ADAAG: The side wall grab bar shall be 42 inches long minimum, located 12 inches maximum from the rear wall and extending 54 inches minimum from the rear wall (604.5.1).

The bottom edge of the mirror's reflecting surface is 44 inches above the floor.

ADAAG: Mirrors shall be installed with the bottom edge of the reflecting surface 40 inches maximum above the floor (603.3).

The main locker rooms do not have an ambulatory accessible toilet compartment.

ADAAG: In addition to the wheelchair accessible toilet compartment required to comply with 604.8.1, at least one ambulatory accessible toilet compartment complying with 604.8.2 is required where six or more toilet compartments are provided, or where the combination of urinals and water closets totals six or more fixtures (213.3.1).

No hand-held shower unit with hose is provided in the showers.

ADAAG: A shower spray unit with a hose 59 inches long minimum that can be used both as a fixed shower head and as a hand-held shower shall be provided in accessible shower compartments (608.6).

Drinking Fountains

All of the drinking fountains are wheelchair accessible models. There are no hi-lo fountains or models for standing persons.

ADAAG: Two drinking fountains minimum, or a hi-lo fountain, shall be provided on a floor. Half of the fountains shall be for standing persons (211.2). Spout outlets of drinking fountains for standing persons shall be between 38 and 43 inches above the floor (602.7).